



Technical Service Bulletin

Technical Service Bulletin: tsb103435

Released Date: 20-Apr-2009

Aftercooler Assembly Procedure, Install Section Revision

Aftercooler Assembly Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the hose clamp torque in the Install section of Procedure 010-002 (Aftercooler Assembly).

Related Procedures

56-010-002-tr
(/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)

Aftercooler Assembly
(/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)

Last Modified: 20-Apr-2009