



Technical Service Bulletin

Technical Service Bulletin: tsb103497

Released Date: 30-Apr-2009

Flywheel Housing Procedure, Install Section Revision

Flywheel Housing Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a torque value for the rear engine mounts in the Install section of Procedure 016-006 (Flywheel Housing) in Section 16.

Related Procedures

56-016-006-tr
(/qs3/pubsys2/xml/en/procedures/56/56-016-006-tr.html)

Flywheel Housing
(/qs3/pubsys2/xml/en/procedures/56/56-016-006-tr.html)

Last Modified: 30-Apr-2009