



Technical Service Bulletin

Technical Service Bulletin: tsb103513

Released Date: 22-May-2009

Turbocharger Procedure, V-Band Clamp Torque Revision

Turbocharger Procedure, V-Band Clamp Torque Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the torque value for the V-band clamp on the HX02 turbocharger in the Assemble section of Procedure 010-033 (Turbocharger) in the QSK45 and QSK60 Service Manual, Bulletin 4021530.

Related Procedures

56-010-033
(/qs3/pubsys2/xml/en/procedures/56/56-010-033.html)

Turbocharger
(/qs3/pubsys2/xml/en/procedures/56/56-010-033.html)

Last Modified: 22-May-2009