



Technical Service Bulletin

Technical Service Bulletin: tsb103804

Released Date: 29-May-2009

Cylinder Block and Liner Seats Procedure, Measure Section Revision

Cylinder Block and Liner Seats Procedure, Measure Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Measure section of Procedure 001-027 (Cylinder Block and Liner Seats) for Service Manual, Bulletin 4021530. The minimum specification for the Counterbore Diameter - Lower Press Fit Diameter has been changed from a specification of 181.47 mm [7.144 in] to a new specification of 181.74 mm [7.155 in].

Related Procedures

56-001-027
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Cylinder Block and Liner Seats
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Last Modified: 29-May-2009