



Technical Service Bulletin

Technical Service Bulletin: tsb103819

Released Date: 23-Jun-2009

Cylinder Block Procedure, Head Deck Surface Section Revision

Cylinder Block Procedure, Head Deck Surface Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the deck height measurements in the Head Deck Surface section of Procedure 001-026 (Cylinder Block) in Section 1 of the QSK45 and QSK60 Series Service Manual, Bulletin 4021530.

Related Procedures

102-001-026
(/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)

Cylinder Block
(/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)

Last Modified: 23-Jun-2009