



Technical Service Bulletin

Technical Service Bulletin: tsb103825

Released Date: 11-Jun-2009

Cylinder Block Service Tools Addition

Cylinder Block Service Tools Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a new service tool, Part Number 4919357, to Procedure 022-001 (Service Tools). This new tool is used to remove main bearings caps.

Related Procedures

56-022-001_01
(/qs3/pubsys2/xml/en/procedures/56/56-022-001_01.html)

Service Tools - Cylinder Block
(/qs3/pubsys2/xml/en/procedures/56/56-022-001_01.html)

Last Modified: 11-Jun-2009