



Technical Service Bulletin

Technical Service Bulletin: tsb103850	Released Date: 25-Apr-2012
Lubricating Oil Cooler Cover Procedure, Install Section Revision	

Lubricating Oil Cooler Cover Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Install section of Procedure 007-045 (Lubricating Oil Cooler Cover) in the QSK45 and QSK60 Service Manual, Bulletin 4021530, to include the use of Loctite™ 271, Part Number 3375068, on the oil cooler stud threads on the oil cooler cover. This change is due to the introduction of the edge-molded oil cooler stud gasket.

Note : The new lubricating oil cooler mounting stud gasket is being introduced with a separate Service/Parts Topic. Also, Procedure 007-045 (Lubricating Oil Cooler Cover) in the following bulletins is being revised using two separate Service/Parts Topics:

- QSK78 Series Engines Troubleshooting and Repair Manual, Bulletin 3666727
- Industrial QSK45G and QSK60G Series Engines Troubleshooting and Repair Manual, Bulletin 4021383.

Last Modified: 25-Apr-2012
