



Technical Service Bulletin

Technical Service Bulletin: tsb103917

Released Date: 04-Aug-2009

Engine Lifting Brackets Procedure, Multiple Section Revisions

Engine Lifting Brackets Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 016-001 (Engine Lifting Brackets) in Section 16 of QSK45 and QSK60 Series Service Manual, Bulletin 4021530.

New capscrews are required after each removal of the engine lifting brackets.

Related Procedures

56-016-001
(/qs3/pubsys2/xml/en/procedures/56/56-016-001.html)

Engine Lifting Brackets
(/qs3/pubsys2/xml/en/procedures/56/56-016-001.html)

Last Modified: 04-Aug-2009