



Technical Service Bulletin

Technical Service Bulletin: tsb103920

Released Date: 04-Sep-2009

Cylinder Head Procedure, Assemble Section Revision

Cylinder Head Procedure, Assemble Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Assemble section of Procedure 002-004 (Cylinder Head). The valve guide installation service tool part numbers have been added.

Related Procedures

56-002-004-tr
(/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)

Last Modified: 04-Sep-2009