



Technical Service Bulletin

Technical Service Bulletin: tsb103962

Released Date: 22-Oct-2009

Lubricating Oil Pump Procedure, Multiple Section Revision

Lubricating Oil Pump Procedure, Multiple Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/Parts Topic introduces multiple revisions to Procedure 007-031 (Lubricating Oil Pump) in the QSK45 and QSK60 Service Manual, Bulletin 4021530.

A Machine section has been added to the procedure. This new section shows a process for reworking the old lubricating oil pumps, Part Numbers 4100710 and 3638986 for the QSK45 engines and Part Numbers 3638987 and 4100711 for the QSK60 engines, to provide a clean oil supply to the lubricating oil pump idler bushing.

Related Procedures

56-007-031-tr
(/qs3/pubsys2/xml/en/procedures/56/56-007-031-tr.html)

Lubricating Oil Pump
(/qs3/pubsys2/xml/en/procedures/56/56-007-031-tr.html)

Last Modified: 22-Oct-2009