



Technical Service Bulletin

Technical Service Bulletin: tsb103984

Released Date: 09-Nov-2009

Lubricating Oil Filter Head Procedure, Assemble Section Revision

Lubricating Oil Filter Head Procedure, Assemble Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-015 (Lubricating Oil Filter Head) for the QSK45 and QSK60 Service Manual, Bulletin 4021530. The adapter installation instructions have been revised.

Related Procedures

56-007-015-tr
(/qs3/pubsys2/xml/en/procedures/56/56-007-015-tr.html)

Lubricating Oil Filter Head
(/qs3/pubsys2/xml/en/procedures/56/56-007-015-tr.html)

Last Modified: 09-Nov-2009