



Technical Service Bulletin

Technical Service Bulletin: tsb103987

Released Date: 02-Nov-2009

Piston and Cylinder Liner Procedure, Install Section Revision

Piston and Cylinder Liner Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts topic introduces a revision to Procedure 001-045 (Piston and Cylinder Liner) in Section 1 of the QSK45 and QSK60 Service Manual, Bulletin 4021530.

Proper connecting rod capscrew and bearing lubrication requirements have been added to the Install section of the procedure.

Related Procedures

56-001-045-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)

Piston and Cylinder Liner
(/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)

Last Modified: 02-Nov-2009