



Technical Service Bulletin

Technical Service Bulletin: tsb103988

Released Date: 02-Nov-2009

Piston and Connecting Rod Assembly Procedure, Multiple Section Revisions

Piston and Connecting Rod Assembly Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-054 in Section 1 of the QSK45 and QSK60 Service Manual, Bulletin 4021530.

Information has been added to indicate this procedure is for angle split connecting rods only.

Information has also been added to specify the lubricant used on the bearings and connecting rod capscrews.

Related Procedures

56-001-054-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)

Piston and Connecting Rod Assembly
(/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)

Last Modified: 02-Nov-2009