



Technical Service Bulletin

Technical Service Bulletin: tsb104011	Released Date: 07-Dec-2009
Symptom Tree t105 (Lubricating Oil Pressure Low), Cause and Correction Step Addition	

Symptom Tree t105 (Lubricating Oil Pressure Low), Cause and Correction Step Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises troubleshooting symptom tree t105 (Lubricating Oil Pressure Low) in Service Manual, QSK45 and QSK60, Bulletin 4021530. The order of inspection has been revised to aid in troubleshooting. An additional Cause and Correction step has been added to check malfunctioning sensors in the common sensor voltage supply circuit.

Lubricating Oil Pressure Low

Last Modified: 07-Dec-2009
