



Technical Service Bulletin

Technical Service Bulletin: tsb104033

Released Date: 22-Jan-2010

(Bearing, Main), Crankshaft, and Cylinder Block Procedure Revisions

(Bearing, Main), Crankshaft, and Cylinder Block Procedure Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the following procedures 001-006 (Bearing, Main), 001-016 (Crankshaft), and 001-026 (Cylinder Block) in Section 1 for the following publications:

- Service Manual, QSK45 and QSK60, Bulletin 4021530
- Troubleshooting and Repair Manual, Industrial QSK45 and QSK60G Series Engines, Bulletin 4021383
- Troubleshooting and Repair Manual, QSK60G Generator CM700, Bulletin 4021396.

The procedures include information for the removal and installation of the QSK60 fully counterweighted crankshaft.

Related Procedures

56-001-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)	Bearings, Main (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)
56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)	Crankshaft (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
102-001-026 (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)	Cylinder Block (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)

