



Technical Service Bulletin

Technical Service Bulletin: tsb104184

Released Date: 04-May-2010

Revision to Engine Installation Procedure

Revision to Engine Installation Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 000-002 (Engine Installation) in the QSK45 and QSK60 Service Manual, Bulletin 4021530. Instructions to recheck the crankshaft endfloat have been added.

Related Procedures

56-000-002
(/qs3/pubsys2/xml/en/procedures/56/56-000-002.html)

Engine Installation
(/qs3/pubsys2/xml/en/procedures/56/56-000-002.html)

Last Modified: 04-May-2010