



Technical Service Bulletin

Technical Service Bulletin: tsb104222

Released Date: 27-May-2010

Fan Drive Idler Arm Assembly Procedure, Multiple Section Revisions

Fan Drive Idler Arm Assembly Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a revision to Procedure 008-029 (Fan Drive Idler Arm Assembly) in the QSK45 and QSK60 Service Manual, Bulletin Number 4021530 and the QSK78 Service Manual, Bulletin 3666727.

- The Clean and Inspect for Reuse section (4021530) and Inspect for Reuse section (3666727) were modified to clarify the dimensions of the different types of shafts used.
- The Assemble section was modified to include details on greasing the bearings on the slide arm type adjuster.

Related Procedures

50-008-029-tr (/qs3/pubsys2/xml/en/procedures/50/50-008-029-tr.html)	Fan Drive Idler Arm Assembly (for QSK45 and QSK60 engines) (/qs3/pubsys2/xml/en/procedures/50/50-008-029-tr.html)
56-008-029-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)	Fan Drive Idler Arm Assembly (for QSK78 engines) (/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)

Last Modified: 27-May-2010

