



Technical Service Bulletin

Technical Service Bulletin: TSB110196

Released Date: 25-Jul-2011

New QSK60 and QSK78 Capscrews

New QSK60 and QSK78 Capscrews

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

New capscrews were released to replace capscrews as part of a continuous improvement project. New drawings have been created for the new capscrews. Listed assemblies and options have been updated and previous capscrews have been obsoleted and a supercession was established. Some capscrews were found **not** to need the special coating, so they were replaced with a suitable standard coated fastener.

The capscrews below were obsoleted without a supercession being setup. The parts listed under the new part number header are the replacement capscrews, which should be ordered if the old part number is requested. Table 1 lists the capscrew location, new part number, and old part number.

Table 1: Capscrew Supercession

Capscrew (Location on engine)	New Part Number	Old Part Number
QSK45 Full Flow Filter Head	3644471	4080578
Inside QSK60 Thermostat Housing	3900633	4098089
QSK60 HPI Turbocharger Oil Plumbing	3644532	3349461
QSK78 Air Cross-over	3082439	3089356

Document History

Date	Details
2011-6-27	Module Created

