



Technical Service Bulletin

Technical Service Bulletin: TSB140045

Released Date: 29-Jul-2014

New Engine Speed Sensors

New Engine Speed Sensors

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces new engine speed sensors on multiple High Horsepower engines.

The purpose of this change is to make the sensors more robust to oil intrusion in wet applications.

There is no change to the installation or removal procedure due to these sensor changes.

Table 1 lists the old and new part numbers.

Table1: Engine Speed Sensor Part Numbers

Old Sensor	New Sensor
2872354	4327234
2872356	4327236
2872358	4327238
2872359	4327239
2872362	4326596

Document History

Date	Details
2014-4-14	Module Created
2014-7-26	none

