



Technical Service Bulletin

Technical Service Bulletin: TSB101046

Released Date: 07-Oct-2010

008-016 (Coolant Thermostat Seal) Procedure Revision

008-016 (Coolant Thermostat Seal) Procedure Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Procedure 008-016 (Coolant Thermostat Seal) in Section 8 in the QSK45 and QSK60 Service Manual, Bulletin 4021530, has been updated to include a new step in the Install section. The new step details how to check for the parallelism of the seal once it has been installed into the counter bore of the thermostat housing.

Document History

Date	Details
2010-8-31	Module Created

Last Modified: 07-Oct-2010