



Technical Service Bulletin

Technical Service Bulletin: TSB101047

Released Date: 07-Oct-2010

011-007 (Exhaust Manifold, Dry) Procedure Revision

011-007 (Exhaust Manifold, Dry) Procedure Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Procedure 011-007 (Exhaust Manifold, Dry) in Section 11, in the QSK45 and QSK60 Service Manual, Bulletin 4021530, has been updated to include a new step in the Clean and Inspect for Reuse section. The new step details how to check for the parallelism between the exhaust manifold mating surfaces. This check is an aid to help identify exhaust manifolds that could leak exhaust gases.

Document History

Date	Details
2010-8-31	Module Created

Last Modified: 07-Oct-2010