



Technical Service Bulletin

Technical Service Bulletin: TSB101069

Released Date: 19-Nov-2010

Rocker Lever Adjusting Screw Locking Nut Torque Revision

Rocker Lever Adjusting Screw Locking Nut Torque Revision

Core Issue

The locking nut torque value in Procedure 003-006 (Overhead Set (OBC)) in Section 3, was **not** consistent with other High Horsepower engine design margins.

Confirmation

Procedure 003-006 (Overhead Set (OBC)) in Section 3, has been updated to revise the rocker lever adjusting screw locking nut torque value.

- QSK45 and QSK60 Service Manual, Bulletin 4021530
- Industrial QSK45G and QSK60G Series Engines, Troubleshooting and Repair Manual, Bulletin 4021383
- QSK60G Generator CM700 Troubleshooting and Repair Manual, Bulletin 4021396.

Resolution

The locking nut torque value has been increased to align with other High Horsepower engine design margins.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2010-10-13	Module Created

Last Modified: 19-Nov-2010

