



Technical Service Bulletin

Technical Service Bulletin: TSB101104

Released Date: 21-Dec-2010

QSK60 Construction Engine Crankcase Breather Hoses

QSK60 Construction Engine Crankcase Breather Hoses

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces new crankcase breather hoses for QSK60 construction engines. The new crankcase breather hoses are made from a molded rubber material that improves robustness.

The engine serial number first is 33184181. The build date is 06 December 2010.

Old Part Number	New Part Number
3636947	3643998
3636945	3643999

The new hoses are **only** applicable to the QSK60 construction option numbers shown below.

Option Numbers Affected
BR 6768
BR 6769
BR 6774
BR 6775
BR 6789
BR 6790
BR 6791
BR 6792

Due to this material change in breather hose, the supporting P-clips have been replaced with slightly larger P-clips. They are located in exactly the same locations and positions as before.

Old Part Number	New Part Number	Quantity
4006930	4080234	5

The new hoses are made of molded rubber and have a different appearance than the old hoses. The removal and installation procedures remain the same.

Reference the following procedure in the QSK45 and QSK60 Service Manual, Bulletin 4021530. Refer to Procedure 003-001 in Section 3. (</qs3/pubsys2/xml/en/procedures/56/56-003-001-tr.html>)

Document History

Date	Details
2010-11-30	Module Created

Last Modified: 21-Dec-2010
