



Technical Service Bulletin

Technical Service Bulletin: TSB110053

Released Date: 18-Mar-2011

Gear Housing Installation with Loctite™

Gear Housing Installation with Loctite™

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document revises the installation section of the front gear housing in the following manuals:

- Service Manual, QSK45 and QSK60, Bulletin 4021530 Refer to Procedure 001-033 in Section 1. (</qs3/pubsys2/xml/en/procedures/56/56-001-033-tr.html>)
- Troubleshooting and Repair Manual, QSK45G and QSK60 Industrial, Bulletin 4021383. Refer to Procedure 001-033 in Section 1. (</qs3/pubsys2/xml/en/procedures/84/84-001-033-tr.html>)
- Troubleshooting and Repair Manual, QSK78 Series Engines, Bulletin 3666727. Refer to Procedure 001-033 in Section 1. (</qs3/pubsys2/xml/en/procedures/50/50-001-033.html>)

The revision is to include the use of Loctite™ 242, Part Number 3824040, or equivalent, when installing the capscrews that retain the gear housing to the engine block.

Loctite™ 242 is presently being used during production assembly at the Daventry Engine Plant. The Loctite™ 242 will be replaced by capscrews with a Loctite™ patch applied to the threads in the near future. In service, if new capscrews are being used that have the Loctite™ patch already applied to the threads, it is **not** required to also use Loctite™ 242 during assembly.

Loctite™ 242 was implemented on the gear housing capscrews for QSK45 and QSK60 and QSK60 Gas engines at engine serial number (ESN) first 33184857 on 08-Feb-2011 and on QSK78 engines at ESN first 66301560 on 09-Feb-2011.

Document History

Date	Details
2011-2-22	Module Created

