



# Technical Service Bulletin

Technical Service Bulletin: TSB110073

Released Date: 21-Mar-2011

ECM and Engine Distance Offset Issue with INSITE™ Electronic Service Tool

## ECM and Engine Distance Offset Issue with INSITE™ Electronic Service Tool

### Core Issue

INSITE™ 7.4.2 and earlier versions do **not** calculate and display the cumulative information for ECM and Engine Distance Offsets correctly.

The ECM Distance Offset and Engine Distance Offset should be added to the Trip Information - All Trips (Cumulative) ECM Distance and Engine Distance, respectively, to display a total value in Trip Information.

### Confirmation

After an ECM Distance Offset or an Engine Distance Offset is entered, the value in Trip Information - All Trips (Cumulative) for ECM Distance or Engine Distance does **not** change.

### Resolution

This issue will be corrected with INSITE™ 7.5.

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Document History

| Date      | Details        |
|-----------|----------------|
| 2011-3-11 | Module Created |

Last Modified: 21-Mar-2011