



Technical Service Bulletin

Technical Service Bulletin: TSB190051

Released Date: 13-May-2020

Alternator Bracket Replacement Parts Lists

Alternator Bracket Replacement Parts Lists

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- HSK78G CM2358 K129G
- QSK45 CM500
- QSK45G
- QSK60 CM2150 MCRS
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K133
- QSK60 CM500
- QSK60 CM850 MCRS
- QSK60 G
- QSK60 G CM2358 K110
- QSK78 CM2250 K104
- QSK78 CM2350 K126
- QSK78 CM2350 K137
- QSK78 CM500

Description of Change

Charging system alternator brackets, Part Numbers 4086629, 4016218, 4100808, and 4001232 are being obsoleted. This document provides instruction on replacing existing alternator brackets with new charging system alternator brackets and necessary associated components if applicable.

Service Instructions

Replace existing charging system alternator bracket with new charging system alternator bracket and all associated components as specified in Tables 1, 2, 3, 4, and 5 below.

Service Parts Availability

Service parts are available. See Tables 1, 2, 3, 4, and 5 below.

Table 1, Service Parts for 45L and 60L Engines

Replacing Existing Part Number 4016218 with New Part Number 3638017

Part Number	Part Description	Quantity
106289	Hexagon Head Cap Screw	2
3332242	Hexagon Flange Head Cap Screw	4
3093936	Hexagon Flange Head Cap Screw	1
3901249	Hexagon Flange Head Cap Screw	2
3902116	Hexagon Flange Head Cap Screw	2
3910495	Hexagon Flange Head Cap Screw	4
3920447	Hexagon Flange Head Cap Screw	4
3638150	Clamping Plate	1
3691281	Belt Tensioner	1
3638317	Alternator Bracket	1
3638017	Alternator Bracket	1

Table 2, Service Parts for 60L Engines

Replacing Existing Part Number 4100808 with New Part Number 3638015

Part Number	Part Description	Quantity
3332242	Hexagon Flange Head Cap Screw	4
3093936	Hexagon Flange Head Cap Screw	1
3901249	Hexagon Flange Head Cap Screw	2
3902116	Hexagon Flange Head Cap Screw	2
3910495	Hexagon Flange Head Cap Screw	3
3920447	Hexagon Flange Head Cap Screw	3
3638150	Clamping Plate	1
3691281	Belt Tensioner	1

Table 2, Service Parts for 60L Engines		
Replacing Existing Part Number 4100808 with New Part Number 3638015		
Part Number	Part Description	Quantity
3638015	Alternator Bracket	1
Table 3, Service Parts for 45L Engines		
Replacing Existing Part Number 4086629 with New Part Number 3638016		
Part Number	Part Description	Quantity
S150	Hexagon Head Cap Screw	1
3093936	Hexagon Flange Head Cap Screw	1
3332242	Hexagon Flange Head Cap Screw	4
3901249	Hexagon Flange Head Cap Screw	2
3902116	Hexagon Flange Head Cap Screw	4
3910495	Hexagon Flange Head Cap Screw	3
3920447	Hexagon Flange Head Cap Screw	3
3638150	Clamping Plate	1
3691281	Belt Tensioner	1
3638016	Alternator Bracket	1
Table 4, Service Parts for 60L Engines		
Replacing Existing Part Number 4086629 with New Part Number 3638016		
Part Number	Part Description	Quantity
S150	Hexagon Head Cap Screw	1
3093936	Hexagon Flange Head Cap Screw	1
3332242	Hexagon Flange Head Cap Screw	4
3901249	Hexagon Flange Head Cap Screw	2
3902116	Hexagon Flange Head Cap Screw	2
3910495	Hexagon Flange Head Cap Screw	3

Table 4, Service Parts for 60L Engines		
Replacing Existing Part Number 4086629 with New Part Number 3638016		
Part Number	Part Description	Quantity
3920447	Hexagon Flange Head Cap Screw	5
3638150	Clamping Plate	1
3691281	Belt Tensioner	1
3638016	Alternator Bracket	1
Table 4, Service Parts for 45L and 60L Engines		
Replacing Existing Part Number 4001232 with New Part Number 4100619		
Part Number	Part Description	Quantity
3093936	Hexagon Flange Head Cap Screw	1
3332242	Hexagon Flange Head Cap Screw	4
3336571	Lock Nut	4
3420833	Double End Plain Stud	4
3691281	Belt Tensioner	1
3638150	Clamping Plate	1
3639064	Alternator Bracket	1
3910495	Hexagon Flange Head Cap Screw	3
3910540	Hexagon Flange Head Cap Screw	1
3920447	Hexagon Flange Head Cap Screw	5
4100619	Alternator Bracket	1
Table 4, Service Parts for 78L Engines		
Replacing Existing Part Number 4001232 with New Part Number 4100619		
Part Number	Part Description	Quantity
3093936	Hexagon Flange Head Cap Screw	1
3332242	Hexagon Flange Head Cap Screw	4
3336571	Lock Nut	4
3420833	Double End Plain Stud	4
3691281	Belt Tensioner	1
3638150	Clamping Plate	1
3639064	Alternator Bracket	1

Table 4, Service Parts for 78L Engines		
Replacing Existing Part Number 4001232 with New Part Number 4100619		
Part Number	Part Description	Quantity
3910495	Hexagon Flange Head Cap Screw	3
3920447	Hexagon Flange Head Cap Screw	5
4100619	Alternator Bracket	1

Document History

Date	Details
2019-3-27	Module Created
2020-5-7	Non-Product Problem Solving (PPS)