



Technical Service Bulletin

Technical Service Bulletin: TSB220129

Released Date: 23-Jul-2026

Cylinder Head Intake Valve Stem Seal Change

Cylinder Head Intake Valve Stem Seal Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 MCRS

Description of Change

A new cylinder head part number has been released following a change of intake valve stem seal.

Reason for Change

A new valve stem seal has been implemented on intake side to increase lubricating oil flow and reduce valve guide wear over the life of the cylinder head, preventing excessive guide wear requiring early cylinder head changes.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Cylinder Head	5635345	Yes	Yes	5694550

Part Inventory Action

Existing cylinder head part numbers have been built with new valve stem seal under deviation since August 2020 and the change in part number is purely for tracing purposes. Continue to use existing cylinder head part number until no longer available and superseded by new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN First (built with new cylinder head, Part Number 5694550)	Build Date ¹	Plant
33229561	26 August 2022	Daventry
¹ Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2022-6-21	Module Created
2022-7-25	Updated ESN first.
2026-6-9	Updated Production Information