



Technical Service Bulletin

Technical Service Bulletin: TSB220223

Released Date: 07-Nov-2022

New Heatshield Capscrew

New Heatshield Capscrew

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 MCRS

Description of Change

This document announces a new capscrew for the heatshield. New capscrew is longer to achieve a more robust joint.

Reason for Change

Heatshield capscrows have been found to be missing or loose, to achieve an improved bolted joint, a new capscrew/torque combination will be implemented.

Service Instructions

The new capscrew torqued up to 54 N•m [40 ft-lb].

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Capscrew	3643856	No	No	5538544

Part Identification

- Part number 5538544 require a 10mm socket.
- Part number 3643856 requires a 16mm socket.

Publications Affected

Table 3, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Operations and maintenance manual	QSK60 CM2150 MCRS	3666260	Heat Shield	Refer to Procedure 011-032 (/qs3/pubsys2/xml/en/procedures/56/56-011-032.html)	4

Document History

Date	Details
2022-11-2	Module Created