

Manual Change History (4021539) QST30 Service Manual

Date	06-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-003-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-204-003-om-indmar.html)
Procedure Title	How to Use the Manual
Update Reason	
Date	25-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-006-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-204-006-om-indmar.html)
Procedure Title	General Safety Instructions
Update Reason	
Date	25-Jan-2010
Section	Section 1 - Operating Instructions
Procedure Number	99-101-999-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-101-999-om-indmar.html)
Procedure Title	Operating Instructions - Overview
Update Reason	
Date	25-Jan-2010
Section	Section 1 - Operating Instructions
Procedure Number	99-101-008-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-101-008-om-indmar.html)
Procedure Title	Engine Operating Range
Update Reason	

Date	25-Jan-2010
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-103-002 (/qs3/pubsys2/xml/en/procedures/99/99-103-002.html)
Procedure Title	Drive Belts
Update Reason	
Date	25-Jan-2010
Section	Section V - Maintenance Specifications
Procedure Number	99-018-005 (/qs3/pubsys2/xml/en/procedures/99/99-018-005.html)
Procedure Title	Drive Belt Tension
Update Reason	
Date	25-Jan-2010
Section	Section V - Maintenance Specifications
Procedure Number	99-018-009 (/qs3/pubsys2/xml/en/procedures/99/99-018-009.html)
Procedure Title	Capscrew Markings and Torque Values
Update Reason	
Date	04-Feb-2010
Section	Section 1 - Operating Instructions
Procedure Number	99-101-015-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-101-015-om-indmar.html)
Procedure Title	Operating the Engine
Update Reason	
Date	18-Mar-2010
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-007-009 (/qs3/pubsys2/xml/en/procedures/18/18-007-009.html)
Procedure Title	Lubricating Oil Dipstick
Update Reason	

Date	24-Mar-2010
Section	Section i - Introduction
Procedure Number	99-204-009 (/qs3/pubsys2/xml/en/procedures/99/99-204-009.html)
Procedure Title	Acronyms and Abbreviations
Update Reason	
Date	07-Jan-2011
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-013-005-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-013-005-om-ind.html)
Procedure Title	Drive Belt, Alternator
Update Reason	Added information for captive fasteners on alternator belt guard.
Date	07-Jan-2011
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-008-001-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-001-om-ind.html)
Procedure Title	Belt Guard
Update Reason	Added to Section A.
Date	23-Mar-2011
Section	Section 2 - Maintenance Guidelines
Procedure Number	18-102-002-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-102-002-om-ind.html)
Procedure Title	Maintenance Schedule
Update Reason	Updated to todays standards with minor edits.

Date	28-Sep-2011
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-008-087-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-087-om-ind.html)
Procedure Title	Cooling Fan Belt Tensioner
Update Reason	Added procedure to outline and manual.
Date	20-Dec-2011
Section	Section V - Maintenance Specifications
Procedure Number	102-018-003 (/qs3/pubsys2/xml/en/procedures/102/102-018-003.html)
Procedure Title	Lubricating Oil Recommendations and Specifications
Update Reason	Edited to add the specific oils used in HHP Diesel engines, represented by CES (Cummins engineering standards) and API classification.
Date	25-May-2013
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	18-007-051 (/qs3/pubsys2/xml/en/procedures/18/18-007-051.html)
Procedure Title	Lubricating Oil Analysis
Update Reason	This procedure was added to the outline.
Date	28-Aug-2013
Section	Section V - Maintenance Specifications
Procedure Number	102-018-002 (/qs3/pubsys2/xml/en/procedures/102/102-018-002.html)
Procedure Title	Fuel Recommendations and Specifications
Update Reason	Updated fuel specifications.

Date	01-Apr-2015
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	57-016-002-tr (/qs3/pubsys2/xml/en/procedures/57/57-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	Procedure has been updated with currently available greases recommendations.
Date	08-Apr-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-018 (/qs3/pubsys2/xml/en/procedures/57/57-008-018.html)
Procedure Title	Cooling System
Update Reason	Added directions to allow the engine to cool before draining the coolant.
Date	05-May-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-026-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-026-tr.html)
Procedure Title	Cylinder Block
Update Reason	Added main bearing cap and main bearing bore saddle inspection steps to Inspect for Reuse steps.
Date	07-May-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-111 (/qs3/pubsys2/xml/en/procedures/57/57-008-111.html)
Procedure Title	Pulley, Fan Idler
Update Reason	Updated grease(s) recommendations.

Date	07-May-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-036-tr (/qs3/pubsys2/xml/en/procedures/57/57-008-036-tr.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	Updated grease(s) recommendations.
Date	07-Aug-2015
Section	Section 9 - Drive Units - Group 09
Procedure Number	57-009-019 (/qs3/pubsys2/xml/en/procedures/57/57-009-019.html)
Procedure Title	Hydraulic Pump Drive Gear and Shaft
Update Reason	Added procedure to outline for rebuild of hydraulic drive gear and shaft.
Date	19-Aug-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-007-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	Added thrust bearing retaining pin specification.
Date	19-Aug-2015
Section	Section 9 - Drive Units - Group 09
Procedure Number	57-009-016-tr (/qs3/pubsys2/xml/en/procedures/57/57-009-016-tr.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	Added a reference to a new procedure 009-019 Hydraulic Pump Drive Gear and Shaft.

Date	26-Aug-2015
Section	Section 1 - Cylinder Block
Procedure Number	57-001-026-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-026-tr.html)
Procedure Title	Crankshaft
Update Reason	Updated max crankshaft connecting rod diameter from 99.97 to 100.00 mm.
Date	27-Oct-2015
Section	Section 14 - Engine Testing - Group 14
Procedure Number	57-014-008 (/qs3/pubsys2/xml/en/procedures/57/57-014-008.html)
Procedure Title	Engine Testing (In Chassis)
Update Reason	
Date	28-Mar-2016
Section	Section 22- Service Tools
Procedure Number	57-022-001_1 (/qs3/pubsys2/xml/en/procedures/57/57-022-001_1.html)
Procedure Title	Service Tools
Update Reason	Added new service tool Part Number 4918212, Piston Ring Compressor.
Date	14-Apr-2016
Section	Section 1 - Piston and Connecting Rod Assembly
Procedure Number	57-001-054-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Revised procedure to include a new Service Tool reference, new Part Number 4918212.

Date	09-Jun-2016
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	57-007-007-tr (/qs3/pubsys2/xml/en/procedures/57/57-007-007-tr.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	Changes have been made to the cleaning recommendations for oil cooler elements.
Date	02-Jan-2017
Section	Section 10 - Air Intake System - Group 10
Procedure Number	57-010-033-tr (/qs3/pubsys2/xml/en/procedures/57/57-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added specifications for the HE851 turbocharger.
Date	24-Mar-2017
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-002-tr (/qs3/pubsys2/xml/en/procedures/57/57-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	Updated to include an inspect and re-use guideline for the drive belt tensioner.
Date	02-Nov-2017
Section	Section 1 - Piston and Connecting Rod Assembly
Procedure Number	57-001-008-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-008-tr.html)
Procedure Title	Camshaft
Update Reason	Updated camshaft bushing graphic to show correct hardware.

Date	02-Nov-2017
Section	Section 1 - Piston and Connecting Rod Assembly
Procedure Number	57-001-010-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-010-tr.html)
Procedure Title	Camshaft Bushing
Update Reason	Updated graphics to show correct hardware. Updated Install and Remove steps to current process.
Date	07-Feb-2019
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	57-003-001-tr (/qs3/pubsys2/xml/en/procedures/57/57-003-001-tr.html)
Procedure Title	Crankcase Breather (External)
Update Reason	Added Warning statement to check for blocked crankcase breather tube to prevent pressure buildup in oil pan.
Date	16-Mar-2020
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	57-003-004-tr (/qs3/pubsys2/xml/en/procedures/57/57-003-004-tr.html)
Procedure Title	Overhead Set
Update Reason	Added final torque adjustment to the procedure.
Date	19-Mar-2020
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-008-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-008-tr.html)
Procedure Title	Camshaft
Update Reason	Added additional stepblocks to procedure.

Date	25-Mar-2020
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	57-012-020 (/qs3/pubsys2/xml/en/procedures/57/57-012-020.html)
Procedure Title	Air Compressor (Oil Carryover)
Update Reason	Reconfigured procedure to commonize it.
Date	28-Dec-2020
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-087-tr (/qs3/pubsys2/xml/en/procedures/57/57-008-087-tr.html)
Procedure Title	Cooling Fan Belt Tensioner
Update Reason	Corrected minimum and maximum values listed for Length of Control Rod Assembly.
Date	02-Feb-2021
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	57-016-002-tr (/qs3/pubsys2/xml/en/procedures/57/57-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	Added measuring trunnion clearance and specification table for clearance readings.
Date	09-Jul-2021
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-035 (/qs3/pubsys2/xml/en/procedures/57/57-008-035.html)
Procedure Title	Fan Hub Bracket
Update Reason	Added to manual.

Date	11-Aug-2021
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	57-002-001-tr (/qs3/pubsys2/xml/en/procedures/57/57-002-001-tr.html)
Procedure Title	Crosshead
Update Reason	Added instruction to tighten an additional 20 degrees to remove any residual oil in the cup of the crosshead and ensure proper valve lash.
Date	11-Oct-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	57-006-015-tr (/qs3/pubsys2/xml/en/procedures/57/57-006-015-tr.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	Added General Information section to procedure.
Date	11-Oct-2021
Section	Section 5 - Fuel System - Group 05
Procedure Number	57-005-234 (/qs3/pubsys2/xml/en/procedures/57/57-005-234.html)
Procedure Title	Fuel System Priming
Update Reason	Added procedure to manual.
Date	01-Dec-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-007-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	Added instructions to check thrust bearing retaining pins protrusion on both sides of main bearing cap and to check thrust bearing retaining pins protrusion on the block. Added updated graphics to procedure.

Date	31-Mar-2022
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	57-022-001_02 (/qs3/pubsys2/xml/en/procedures/57/57-022-001_02.html)
Procedure Title	Service Tools
Update Reason	Corrected tool number 3163790 to 6304260 for the Valve Guide Driver.
Date	06-Jul-2022
Section	Section 5 - Fuel System - Group 05
Procedure Number	57-005-083 (/qs3/pubsys2/xml/en/procedures/57/57-005-083.html)
Procedure Title	EHAB Device
Update Reason	Added mention of fuel pump overflow valve.
Date	08-Jul-2022
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	57-006-017-tr (/qs3/pubsys2/xml/en/procedures/57/57-006-017-tr.html)
Procedure Title	Fuel Filter Head
Update Reason	Added instruction to apply Loctite™ 277 or equivalent to the threads in the filter head and to Install the filter head insert. Added accompanying torque value.
Date	08-Jul-2022
Section	Section 5 - Fuel System - Group 05
Procedure Number	57-005-066 (/qs3/pubsys2/xml/en/procedures/57/57-005-066.html)
Procedure Title	Fuel Pump Overflow Valve
Update Reason	Added step and graphic that identifies the overflow/pressure regulator valve, sealing washers, and electrical pigtail connection's location on the EHAB device.

Date	09-Aug-2022
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-023-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-023-tr.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	Removed instructions pertaining to the gear cover from both the Preparatory and Finishing Steps in the procedure.

Date	16-Aug-2022
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-007-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	Added Replace step to procedure.

Date	20-Sep-2022
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	57-002-004-tr (/qs3/pubsys2/xml/en/procedures/57/57-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Added instruction to Clean and Inspect for Reuse steps that if valve seats are being replaced, they must be machined after installation.

Date	13-Oct-2022
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-133 (/qs3/pubsys2/xml/en/procedures/57/57-008-133.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Thermostat Housing
Update Reason	Added procedure to manual.

Date	13-Oct-2022
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-062-tr (/qs3/pubsys2/xml/en/procedures/57/57-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Added to Inspect step that if damage is found on the water pump, it needs to be replaced.
Date	13-Oct-2022
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-165 (/qs3/pubsys2/xml/en/procedures/57/57-008-165.html)
Procedure Title	Low Temperature Aftercooler (LTA) Thermostat Seal
Update Reason	Added procedure to manual.
Date	13-Oct-2022
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-110 (/qs3/pubsys2/xml/en/procedures/57/57-008-110.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Water Outlet Connection
Update Reason	Added procedure to manual.
Date	13-Oct-2022
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-131 (/qs3/pubsys2/xml/en/procedures/57/57-008-131.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Thermostat
Update Reason	Added procedure to manual.

Date	13-Oct-2022
Section	Section 5 - Fuel System - Group 05
Procedure Number	57-003-004-tr (/qs3/pubsys2/xml/en/procedures/57/57-003-004-tr.html)
Procedure Title	Overhead Set
Update Reason	Revised stepblock outlining how to adjust the crosshead located in the Adjust step of the procedure.
Date	21-Feb-2023
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	57-016-004-tr (/qs3/pubsys2/xml/en/procedures/57/57-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	Added procedure to manual.
Date	26-Apr-2023
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-001 (/qs3/pubsys2/xml/en/procedures/57/57-008-001.html)
Procedure Title	Belt Guard
Update Reason	Added procedure to manual.
Date	12-Sep-2024
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	57-022-001_02 (/qs3/pubsys2/xml/en/procedures/57/57-022-001_02.html)
Procedure Title	Service Tools
Update Reason	Corrected tool number 3163429 to 4918644 for the Valve Stem Seal Driver.

Date	01-Oct-2025
Section	Section 10 - Air Intake System - Group 10
Procedure Number	57-010-033-tr (/qs3/pubsys2/xml/en/procedures/57/57-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added step to Install section that if installing new turbocharger to compare orientation of turbocharger compressor housing to the turbocharger being replaced. Added accompanying graphic and additional details.
Date	16-Oct-2025
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	57-007-025-tr (/qs3/pubsys2/xml/en/procedures/57/57-007-025-tr.html)
Procedure Title	Lubricating Oil Pan
Update Reason	Added to procedure to verify the gasket surface with text present ("TS-9016" or "PAN SIDE") is facing toward the lubricating oil pan. Updated capscrew tightening graphic to reflect proper sequence.
Date	12-Nov-2025
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-036-tr (/qs3/pubsys2/xml/en/procedures/57/57-008-036-tr.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	Updated bearing end clearance millimeter maximum specification from 0.0152 mm to the proper value, 0.152 mm.
Date	17-Dec-2025
Section	Section 9 - Drive Units - Group 09
Procedure Number	57-009-008 (/qs3/pubsys2/xml/en/procedures/57/57-009-008.html)
Procedure Title	Charging System Alternator Drive
Update Reason	Added to manual, removed 009-001 and 009-004.

Date	17-Dec-2025
Section	Section 9 - Drive Units - Group 09
Procedure Number	57-009-010 (/qs3/pubsys2/xml/en/procedures/57/57-009-010.html)
Procedure Title	Charging System Alternator Drive Pulley
Update Reason	Added to manual, removed 009-001 and 009-004.
Date	19-Dec-2025
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021539-t047-tr (/qs3/pubsys2/xml/en/manual/4021539/4021539-t047-tr.html)
Procedure Title	Engine Noise Excessive
Update Reason	Fixed link to 009-001 to reference 009-008 instead.
Date	19-Dec-2025
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021539-t006-tr (/qs3/pubsys2/xml/en/manual/4021539/4021539-t006-tr.html)
Procedure Title	Air Compressor Noise is Excessive
Update Reason	Fixed link to 009-001 to reference 009-008 instead.
Date	19-Dec-2025
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-031-tr (/qs3/pubsys2/xml/en/procedures/57/57-001-031-tr.html)
Procedure Title	Gear Cover, Front
Update Reason	Fixed link to 009-004 to reference 009-010 instead.

Date	19-Dec-2025
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	57-001-065 (/qs3/pubsys2/xml/en/procedures/57/57-001-065.html)
Procedure Title	Camshaft End Clearance
Update Reason	Fixed link to 009-001 to reference 009-008 and 009-010 instead.
Date	08-Jan-2026
Section	Section 9 - Drive Units - Group 09
Procedure Number	57-009-091 (/qs3/pubsys2/xml/en/procedures/57/57-009-091.html)
Procedure Title	Offset Accessory Drive
Update Reason	Added procedure to manual.
Date	26-Feb-2026
Section	Section 8 - Cooling System - Group 08
Procedure Number	57-008-195 (/qs3/pubsys2/xml/en/procedures/57/57-008-195.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Water Pump Support Bracket
Update Reason	Added procedure to manual.
Date	24-Apr-2026
Section	Section 10 - Air Intake System - Group 10
Procedure Number	57-010-033-tr (/qs3/pubsys2/xml/en/procedures/57/57-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated HE800 Turbocharger torque information to HE800/HE851 (no lock plates) and HE851 by itself (with lock plates). Also updated the turbocharger impeller inspection to state if the impeller has damage replace turbocharger, not the impeller.

Date	29-Apr-2026
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	57-006-013 (/qs3/pubsys2/xml/en/procedures/57/57-006-013.html)
Procedure Title	Fuel Drain Lines
Update Reason	Added reference to procedures 006-024 and 006-021 into procedure.

Date	29-Apr-2026
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	57-006-024-tr (/qs3/pubsys2/xml/en/procedures/57/57-006-024-tr.html)
Procedure Title	Fuel Supply Lines
Update Reason	Added reference to procedures 006-013 and 006-021 into procedure.

Date	29-Apr-2026
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	57-006-021-tr (/qs3/pubsys2/xml/en/procedures/57/57-006-021-tr.html)
Procedure Title	Fuel Manifold (Drain)
Update Reason	Added reference to procedure 006-013.

Date	29-Apr-2026
Section	Section 5 - Fuel System - Group 05
Procedure Number	57-005-012-tr (/qs3/pubsys2/xml/en/procedures/57/57-005-012-tr.html)
Procedure Title	Fuel Injection Pumps, In-Line
Update Reason	Added instruction to prime fuel system and added reference to procedure 005-234 in section 5 in Finishing Steps.

Date	29-Apr-2026
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	57-006-017-tr (/qs3/pubsys2/xml/en/procedures/57/57-006-017-tr.html)
Procedure Title	Fuel Filter Head
Update Reason	Added instruction to prime fuel system and reference to procedure 005-234 in Remove and Install steps.

Date	26-May-2026
Section	Section 10 - Air Intake System - Group 10
Procedure Number	57-010-033-tr (/qs3/pubsys2/xml/en/procedures/57/57-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated minimum specification for the Turbocharger Turbine Housing Flange Flatness from 0.010 mm to 0.102 mm.

Date	29-May-2026
Section	Section 9 - Drive Units - Group 09
Procedure Number	57-009-092 (/qs3/pubsys2/xml/en/procedures/57/57-009-092.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Water Pump Drive
Update Reason	Added procedure to manual.

Last Modified: 10-Jun-2026
