

Manual Change History (4358403) Dual Fuel Technology DF101 Master Repair Manual

Date	14-May-2015
Section	Back
Procedure Number	4358403-history (/qs3/pubsys2/xml/en/manual/4358403/4358403-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for engine released for use.
Date	02-Mar-2017
Section	Section TA - Troubleshooting Alarm Codes
Procedure Number	330-t02-1004 (/qs3/pubsys2/xml/en/procedures/330/330-t02-1004.html)
Procedure Title	Sd LowGasPressIn
Update Reason	The troubleshooting has been rewritten and has gone through extensive validation with the test panel.
Date	02-Mar-2017
Section	Section TA - Troubleshooting Alarm Codes
Procedure Number	330-t02-1007 (/qs3/pubsys2/xml/en/procedures/330/330-t02-1007.html)
Procedure Title	Sd RegGasPress
Update Reason	The troubleshooting has been rewritten and has gone through extensive validation with the test panel.
Date	03-Mar-2017
Section	Section TA - Troubleshooting Alarm Codes
Procedure Number	330-t02-1008 (/qs3/pubsys2/xml/en/procedures/330/330-t02-1008.html)
Procedure Title	Sd FSOV POC Sw
Update Reason	The troubleshooting has been rewritten and has gone through extensive validation with the test panel.

Date	03-Mar-2017
Section	Section TA - Troubleshooting Alarm Codes
Procedure Number	330-t02-1015 (/qs3/pubsys2/xml/en/procedures/330/330-t02-1015.html)
Procedure Title	Sd Rationality Check
Update Reason	The troubleshooting has been rewritten and has gone through extensive validation with the test panel.

Date	03-Mar-2017
Section	Section TA - Troubleshooting Alarm Codes
Procedure Number	330-t02-1032 (/qs3/pubsys2/xml/en/procedures/330/330-t02-1032.html)
Procedure Title	Sd EGTBankDelta
Update Reason	The troubleshooting has been rewritten and has gone through extensive validation with the test panel.

Date	03-Mar-2017
Section	Section TA - Troubleshooting Alarm Codes
Procedure Number	330-t02-1082 (/qs3/pubsys2/xml/en/procedures/330/330-t02-1082.html)
Procedure Title	Sd Maximum Gas
Update Reason	The troubleshooting has been rewritten and has gone through extensive validation with the test panel.

Date	03-Mar-2017
Section	Section TA - Troubleshooting Alarm Codes
Procedure Number	330-t02-1111 (/qs3/pubsys2/xml/en/procedures/330/330-t02-1111.html)
Procedure Title	DF Not Ready
Update Reason	New troubleshooting tree added to manual.

Date	20-Feb-2025
Section	Section 3 - Routine Maintenance
Procedure Number	330-006-026-tr (/qs3/pubsys2/xml/en/procedures/330/330-006-026-tr.html)
Procedure Title	Injector
Update Reason	Added procedure to manual.

Last Modified: 03-Apr-2025
