



Technical Service Bulletin

Technical Service Bulletin: tsb040013	Released Date: 06-Apr-2004
Bench Calibration Harness Correction	

Bench Calibration Harness Correction

Core Issue

The purpose of this Early Warning is to provide information on how to repair the QST30 bench calibration harness, Part Number 3164458.

Confirmation

QST30.

The QST30 bench calibration harness, Part Number 3164458, was built without the necessary jumper wires required to function properly. This results in an inability to transfer calibrations to the ECM and can result in various fault codes.

All of the QST30 bench calibration harnesses, Part Number 3164458, initially exhibited this problem. **Only** those who have notified Service Products or Service Tools have received the repair components and instructions.

The initial bench calibration harnesses were built incorrectly. Since that time, QST30 bench calibration harnesses with ROM boot have been released. None of the QST30 bench calibration harnesses with ROM boot exhibit this problem.

None.

Resolution

The necessary jumper wires and instructions for installing them are available by contacting Josh Thomas in Cummins Service Tools at (812) 377-1746.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 06-Apr-2004
