



Technical Service Bulletin

Technical Service Bulletin: tsb100490

Released Date: 05-Dec-2006

Water Pump Coolant Seal, Material Change

Water Pump Coolant Seal, Material Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin is to inform the field of a new and improved water pump coolant seal, Part Number 4096426. The new water pump coolant seal incorporates a higher temperature rubber material and is designed to improve the water pump sealing durability. The new water pump coolant seal replaces the old water pump coolant seal, Part Number 3092348. Production use began with engine serial number (ESN) first 37223634.

The new water pump coolant seal is included in the following water pumps and water pump repair kits:

Table 1, Water Pumps and Water Pump Repair Kits

Part Number	Description
4090032	Water pump repair (minor)
4090033	Water pump repair (major)
4090034	Water pump repair
4096427	Water pump
4096429	Water pump

Note : This is a product improvement and is **not** subject to campaign.