



Technical Service Bulletin

Technical Service Bulletin: tsb100587

Released Date: 02-May-2007

New Service Kits for Bosch® Fuel Pumps

New Service Kits for Bosch® Fuel Pumps

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin explains that four QST30 fuel pumps have been obsoleted by Bosch®. See the table below to determine affected fuel pumps.

Refer to Procedure 005-045 for removal and installation instructions of the fuel lift pump. (/qs3/pubsys2/xml/en/procedures/57/57-005-045-tr.html) When installing the mechanical fuel lift pump gasket and mechanical fuel lift pump, tighten the three capscrews to 8 N•m [72 in-lb]. When installing the sealing washer and adapter into the M16 fuel inlet port on the injection pump, tighten to 41 N•m [30 ft-lb].

Pump Type	Obsolete Part Number	New Part Number	Description
P8500 (RB)	3093278	3093637	Pump, Fuel Injection
P8500 (LB)	3093279	3093638	Pump, Fuel Injection
P7100 (RB)	3093280	3093633	Pump, Fuel Injection
P7100 (LB)	3093281	3093634	Pump, Fuel Injection
Additional Parts			
N/A	N/A	3094987	Adapter, Fuel Connector
N/A	N/A	3281602	Washer, Sealing
N/A	N/A	3800695	Kit, Fuel Transfer Pump

Last Modified: 02-May-2007

