



Technical Service Bulletin

Technical Service Bulletin: TSB101045

Released Date: 04-Oct-2018

INSITE™ for CENSE™ Application Missing Some QSK78 Fault Code Descriptions

INSITE™ for CENSE™ Application Missing Some QSK78 Fault Code Descriptions

Core Issue

The root cause for this issue is that fault code information is missing from the necessary resource files for the program.

Confirmation

N/A

Resolution

Download CENSE™ Service Pack 1 from <http://care.cummins.com>, or install it using INSITE™ electronic service tool DVD.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2010-8-31	Module Created
2018-10-4	Quick Fix application:

Last Modified: 04-Oct-2018