



Technical Service Bulletin

Technical Service Bulletin: TSB101053

Released Date: 27-Sep-2010

Piston Reuse Guidelines Update

Piston Reuse Guidelines Update

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces changes and additions to the Inspect for Reuse section of Procedure 001-043 (Piston) in the QST30 Service Manual, Bulletin 4021539.

The changes include new reuse guidelines for:

- Ring grooves
- Piston crown
- Piston pin outside diameter
- Piston pin bore inside diameter
- Piston skirt outside diameter.

Refer to Procedure 001-043 in Section 1. (</qs3/pubsys2/xml/en/procedures/57/57-001-043.html>)

Document History

Date	Details
2010-9-14	Module Created

Last Modified: 27-Sep-2010