



Technical Service Bulletin

Technical Service Bulletin: TSB101106

Released Date: 18-Mar-2011

Error 102 When Installing INSITE™ Electronic Service Tool 7.4.1 on Windows® Vista™/7 PCs

Error 102 When Installing INSITE™ Electronic Service Tool 7.4.1 on Windows® Vista™/7 PCs

Core Issue

Error 102 occurs when trying to install INSITE™ 7.4.1 with the Cummins® INSITE™ Update Manager.

Confirmation

This procedure should be followed after installing INSITE™ 7.4.1.

Resolution

NOTE: This procedure requires administrator rights to complete!!

1. Download and save a copy of the MstFileReplaceUtility.zip to the desktop of the INSITE™ PC.
2. Unzip and extract the **MstFileReplaceUtility.exe** to the desktop of the INSITE™ PC.
3. Double-click the **MstFileReplaceUtility.exe** to run it.
4. The utility will give a message to confirm that the files were copied successfully. Click **OK** on this message.
5. Continue with the INSITE™ updates installation using the Cummins INSITE™ Update Manager.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2010-12-2	Module Created

Last Modified: 18-Mar-2011

