



Technical Service Bulletin

Technical Service Bulletin: tsb101210	Released Date: 24-Oct-2002
Engine Datalinks	

Engine Datalinks

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic supersedes topic 99T19-6 and topic 99T19-6A; replace 99T19-6 and 99T19-6A with this one. This procedure describes connecting engine datalinks to electronic service tools. This procedure provides a list of the contents of the INLINE™, INLINE™ I and INLINE™ II datalink kits. It also describes datalink adapters, datalink connectors, and connecting to an Electronic Control Module (ECM).

Last Modified: 24-Oct-2002
