



Technical Service Bulletin

Technical Service Bulletin: tsb102004	Released Date: 19-Dec-2006
New Fault Codes 772 and 773	

New Fault Codes 772 and 773

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces Fault Codes 772 and 773 for the QST30 engine.

Left Bank Needle Lift Sensor Reading Is Not Being Detected or Is Out of Range. Right Bank Needle Lift Sensor Reading Is Not Being Detected or Is Out of Range.

Last Modified: 19-Dec-2006
