



Technical Service Bulletin

Technical Service Bulletin: tsb103229

Released Date: 26-Nov-2008

Procedure 006-026 (Injector), Replace Section Revision

Procedure 006-026 (Injector), Replace Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the Procedure 006-026 (Injector) to Section 10 of the Operation and Maintenance Manual K38, K50, QSK38 and QSK50, Bulletin 3810497. This procedure recommends injector replacement at engine half life to rebuild for both the mechanically and electronically actuated injectors.

Related Procedures

28-006-026-om
(/qs3/pubsys2/xml/en/procedures/28/28-006-026-om.html)

Injector
(/qs3/pubsys2/xml/en/procedures/28/28-006-026-om.html)

Last Modified: 26-Nov-2008