



# Technical Service Bulletin

---

|                                          |                            |
|------------------------------------------|----------------------------|
| Technical Service Bulletin: tsb103619    | Released Date: 23-Sep-2009 |
| Fault Code 2727, Guided Step 2D Addition |                            |

## Fault Code 2727, Guided Step 2D Addition

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

This Service/Parts Topic adds Guided Step 2D to Fault Code 2727, in Section TF of the Troubleshooting and Repair Manual QSK38, QSK50 and QSK60 CM850 Modular Common Rail System, Bulletin 4021533.

SAE J1939 Data Link 2 Engine Network - Abnormal Update Rate

---

**Last Modified: 23-Sep-2009**

---