



Technical Service Bulletin

Technical Service Bulletin: tsb103816

Released Date: 21-May-2009

New Lift Pump

New Lift Pump

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a new lift pump for the QST30 engine and supersedes Service/Parts Topic 09T5-4.

The new lift pump has a hardened gerotor with an improved tolerance for debris. The new lift pump, Part Number 4975617, went into production with engine serial number (ESN) First 37240363.

Old Part Number	New Part Number	Description
4975518	4975617	PUMP, FUEL TRANSFER

Note : This is a product improvement and is not subject to campaign.

Related Procedures

(/qs3/pubsys2/xml/en/procedures//.html)

(/qs3/pubsys2/xml/en/procedures//.html)

Last Modified: 21-May-2009