



Technical Service Bulletin

Technical Service Bulletin: tsb104078

Released Date: 17-Feb-2010

Water Pump and LTA Water Pump Procedures, Multiple Section Revisions

Water Pump and LTA Water Pump Procedures, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 008-062 (Water Pump) and Procedure 008-109 (Low-Temperature Aftercooler (LTA) Water Pump)) in Section 8 in Service Manual, K38, K50, QSK38, and QSK50, Bulletin 4021528. The Mechanically Actuated Injector sections have been renamed to Jacket and the Electronically Actuated Injector sections have been renamed to Dual Impeller. The Mechanically Actuated Injector section name was removed from Procedure 008-109 in Section 8.

Related Procedures

28-008-062-tr (/qs3/pubsys2/xml/en/procedures/28/28-008-062-tr.html)	Water Pump (/qs3/pubsys2/xml/en/procedures/28/28-008-062-tr.html)
28-008-109-tr (/qs3/pubsys2/xml/en/procedures/28/28-008-109-tr.html)	Low-Temperature Aftercooler (LTA) Water Pump (/qs3/pubsys2/xml/en/procedures/28/28-008-109-tr.html)

Last Modified: 17-Feb-2010