



Technical Service Bulletin

Technical Service Bulletin: TSB110223

Released Date: 27-Sep-2011

QST30 Industrial Calibration Revision for Fault Code 772/773 Lamp Strategy Update

QST30 Industrial Calibration Revision for Fault Code 772/773 Lamp Strategy Update

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces a change in calibrations for QST30 Industrial engines. The calibration change was made to correct the lamp strategy for Fault Codes 772 and 773. Reference Table 1 for previous and revised calibrations.

In the previous revisions of each calibration, an amber lamp lit when Fault Code 772 or 773 became active. In the revised calibrations, no lamps light when Fault Code 772 or 773 becomes active. Fault Codes 772 and 773 will continue to be logged with the ECM and can still be used for troubleshooting purposes. The lamp strategy of the revised calibrations meets Cummins® Engineering Standards.

The new calibrations were installed in production engines built on or after July 2011.

Table 1: Old and New Calibrations

Previous Calibration	Revised Calibration
K50176.02	K50176.03
K50186.00	K50186.01
K50187.00	K50187.01
K50017.21	K50017.22
K50024.22	K50024.23
K50043.20	K50043.21
K50054.19	K50054.20
K50055.17	K50055.18
K50057.14	K50057.15
K50059.12	K50059.13
K50061.10	K50061.11
K50061.15	K50061.16

Table 1: Old and New Calibrations

Previous Calibration	Revised Calibration
K50063.13	K50063.14
K50065.13	K50065.14
K50066.12	K50066.13
K50067.11	K50067.12
K50069.13	K50069.14
K50070.10	K50070.11
K50071.10	K50071.11
K50072.04	K50072.05
K50072.09	K50072.10
K50073.04	K50073.05
K50073.09	K50073.10
K50076.09	K50076.10
K50077.04	K50077.05
K50077.09	K50077.10
K50082.10	K50082.11
K50083.09	K50083.10
K50084.08	K50084.09
K50085.09	K50085.10
K50088.07	K50088.08
K50092.02	K50092.03
K50092.07	K50092.08
K50093.02	K50093.03
K50093.06	K50093.07
K50094.02	K50094.03
K50094.07	K50094.08
K50103.02	K50103.03
K50123.02	K50123.03
K50126.01	K50126.02
K50137.00	K50137.01
K50180.00	K50180.01
K50074.10	K50074.11
K50075.11	K50075.12
K50078.09	K50078.10
K50086.07	K50086.08
K50089.07	K50089.08

Table 1: Old and New Calibrations	
Previous Calibration	Revised Calibration
K50090.06	K50090.07
K50091.07	K50091.08
K50095.07	K50095.08
K50096.08	K50096.09
K50097.09	K50097.10
K50098.03	K50098.04
K50099.03	K50099.04
K50101.03	K50101.04
K50105.02	K50105.03
K50106.04	K50106.05
K50110.02	K50110.03
K50118.01	K50118.02
K50131.01	K50131.02
K50133.01	K50133.02
K50136.01	K50136.02
K50164.00	K50164.01
K50183.01	K50183.02
K50028.19	K50028.20
K50062.10	K50062.11
K50064.09	K50064.10
K50068.06	K50068.07
K50080.05	K50080.06
K50081.06	K50081.07
K50087.04	K50087.05
K50100.03	K50100.04
K50102.03	K50102.04
K50104.01	K50104.02
K50113.00	K50113.01
K50130.01	K50130.02
K50167.02	K50167.03
K50024.30	K50024.31
K50045.22	K50045.23
K50141.00	K50141.01
K50142.00	K50142.01
K50143.01	K50143.02

Table 1: Old and New Calibrations	
Previous Calibration	Revised Calibration
K50144.00	K50144.01
K50145.00	K50145.01
K50146.00	K50146.01
K50147.01	K50147.02
K50148.00	K50148.01
K50149.00	K50149.01
K50150.02	K50150.03
K50151.00	K50151.01
K50152.00	K50152.01
K50153.00	K50153.01
K50154.00	K50154.01
K50155.01	K50155.02
K50156.01	K50156.02
K50157.00	K50157.01
K50158.00	K50158.01
K50159.00	K50159.01
K50162.00	K50162.01
K50163.00	K50163.01
K50166.00	K50166.01
K50171.00	K50171.01
K50172.00	K50172.01
K50173.01	K50173.02
K50174.01	K50174.02
K50175.00	K50175.01
K50177.01	K50177.02
K50178.00	K50178.01
K50179.00	K50179.01
K50181.00	K50181.01
K50182.00	K50182.01
K50161.02	K50161.03
K50014.20	K50014.21
K50132.01	K50132.02
K50160.00	K50160.01
K50139.01	K50139.02
K50140.01	K50140.02

Table 1: Old and New Calibrations	
Previous Calibration	Revised Calibration
K50165.00	K50165.01
K50169.00	K50169.01
K50170.00	K50170.01
K50188.00	K50188.01
K50189.00	K50189.01

Document History

Date	Details
2011-7-28	Module Created
2011-8-31	QSOL Quick Fix Reason: Incorrect Part Number Notes: none
2011-9-26	QSOL Quick Fix Reason: Incorrect Part Number Notes: Two calibrations are missing from list. Please add K50189.00/K50189.01
2011-9-27	QSOL Quick Fix Reason: Incorrect Part Number Notes: none