



Technical Service Bulletin

Technical Service Bulletin: TSB120116

Released Date: 23-Apr-2012

New QSK38, QSK50, and QSK60 Engine Speed Sensor

New QSK38, QSK50, and QSK60 Engine Speed Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of new engine speed sensors for the QSK38, QSK50, and QSK60 engines to help prevent occurrences of Fault Code 689.

The following improvements have been applied to the new speed sensor:

- Reduced variation in air gap switching capability between sensors
- Increased air gap switching capability.

The new engine speed sensor can be identified by having a dark blue body. Previous models of the sensor had a light blue, green, or gold body.

The image below illustrates the difference between the new dark blue sensor (1) and the previous light blue sensor (2).



19e01013

Engine Speed Sensors

The new engine speed sensor went into production at Daventry engine plant on 02 May 2012, engine serial number (ESN) first 33192790.

Old Part Number	New Part Number	Description
2872304	4307466	Sensor, position

Document History

Date	Details
2012-4-11	Module Created

Last Modified: 23-Apr-2012
