



Technical Service Bulletin

Technical Service Bulletin: TSB120283

Released Date: 06-Nov-2012

INSITE™ 7.6.0 does not display the ECM values and can not adjust the Intermediate Speed Control Switch Multiplexing parameters.

INSITE™ 7.6.0 does not display the ECM values and can not adjust the Intermediate Speed Control Switch Multiplexing parameters.

Core Issue

INSITE™ 7.6.0 does **not** display and can **not** adjust these Multiplexing parameters for ECMs that support this feature:

- Intermediate Speed Control Increment / Decrement Switch
- Intermediate Speed Control Switch 1
- Intermediate Speed Control Switch 2
- Intermediate Speed Control Switch 3
- Intermediate Speed Control Variable Speed Switch.

Confirmation

None

Resolution

Issue is under investigation.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2012-10-31	Module Created

