



Technical Service Bulletin

Technical Service Bulletin: TSB120308

Released Date: 18-Jan-2013

RS422 and RS232 Interfaces Not Supported by Next Generation CENSE™ CM2330

RS422 and RS232 Interfaces Not Supported by Next Generation CENSE™ CM2330

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces that the next generation CENSE™ CM2330 module will **not** be supporting the RS422 and RS232 interfaces. Instead, it will **only** communicate via the J1939 data link.

This change will affect original equipment manufacturers (OEMs) using RS422 Modular Mining Dispatch system to acquire engine data. Customers currently using this system will need to upgrade to J1939-capable Modular Mining Dispatch.

This change will also affect OEMs using RS232 Radios for Remote Monitoring and OEM cabs that do **not** have a J1939 data link connection port to the engine.

A separate document will be released in Q1 2013 to announce the obsolescence date of the presently used CM530 CENSE™ module.

Affected Part Numbers	
Part Name	Part Number
Engine Control Module	3098771

Document History

Date	Details
2012-12-14	Module Created

Last Modified: 18-Jan-2013

