



Technical Service Bulletin

Technical Service Bulletin: TSB150044

Released Date: 16-Apr-2015

Premium Lubricating Oil Pan Gasket

Premium Lubricating Oil Pan Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces a premium lubricating oil pan gasket to reduce oil pan leak occurrences.

Product Affected

- K50 (All Versions)
- QSK50 (All Versions)

Description of Change

The existing lubricating oil pan gasket has been updated to an improved edge molded gasket.

Reason for Change

To reduce lubricating oil pan leak occurrences.

Customer Communication

Upgrade to the premium lubricating oil pan gasket is recommended if the existing lubricating oil pan gasket is leaking. Upgrade to the premium lubricating oil pan gasket is at the customers discretion.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table1, Lubricating Oil Pan Gasket Part Numbers

Part Description	Existing Part Number	Premium Part Number
Lubricating Oil Pan Gasket	3000630 or 3043213	3641727

Part Structure

The premium part is backward compatible and transparent to assembly.

Part number 3000630 has been obsoleted and superseded by 3043213.

Part number 3043213 will remain available.

Part Inventory Action

None.

Production Status

None.

Associated Publications

Use the following procedure in the K38, K50, QSK38, and QSK50 Service Manual, Bulletin 4021528. Refer to Procedure 007-025 in Section 7. (/qs3/pubsys2/xml/en/procedures/28/28-007-025.html)

Document History

Date	Details
2015-4-2	Module Created

Last Modified: 16-Apr-2015