



Technical Service Bulletin: TSB150077	Released Date: 04-Oct-2018
INSITE™ Electronic Service Tool Version 8.1.0.314 Fails to Create a Work Order/Image	

INSITE™ Electronic Service Tool Version 8.1.0.314 Fails to Create a Work Order/Image

Core Issue

At the end of the calibration download process, when INSITE™ electronic service tool reconnects, the new Work Order window pops up to create a new work order.

After a few seconds, INSITE™ electronic service tool may display:

- "Microsoft Visual C++ Runtime Library > Runtime Error" and no Work Order is created.

This issue may also be encountered after manually creating Work Orders. INSITE™ electronic service tool may:

- Display, "Microsoft Visual C++ Runtime Library > Runtime Error"
- Display, "Error 5201"
- Stop at 25% during a Work Order creation.

This issue happens randomly and may be seen after:

- Multiple successive calibration downloads
- Multiple Work Orders are created

Confirmation

None

Resolution

1. Repeat the process until a Work Order is created successfully.

OR

2. Uninstall INSITE™ electronic service tool version 8.1.0.314, download the INSITE™ electronic service tool version 8.1.0 ISO, and install INSITE™ electronic service tool version 8.0.3 from the downloaded ISO file.

INSITE 8.1.0 ISO can be downloaded using the link below:

Note : <https://www.cummins.com/support/electronic-service-tools-support/insite-support> (<https://www.cummins.com/support/electronic-service-tools-support/insite-support>)

A permanent solution will be provided with the release of INSITE™ electronic service tool version 8.1.1 in the third quarter of 2015.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2015-5-22	Module Created
2018-10-4	Corrected URL

Last Modified: 04-Oct-2018
