



Technical Service Bulletin: TSB170035

Released Date: 25-Apr-2017

Engine Control Module (ECM) Calibration Download Issues Using INSITE™ Electronic Service Tool 8.2.0

Engine Control Module (ECM) Calibration Download Issues Using INSITE™ Electronic Service Tool 8.2.0

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- INSITE™ electronic service tool 8.2.0

Issue

Symptom:

- Erroneous values in logs and Features and Parameters.
- Incorrect values that engine control module (ECM) uses. These are **not** visible or adjustable in INSITE™ electronic service tool, so presence of problem is **not** always apparent.

Root Cause:

- When performing an ECM calibration download with INSITE™ electronic service tool 8.2.0, ECM may **not** receive all values correctly and incorrect data can be written.

Verification

- Because ECM calibration issue may or may **not** manifest itself in a visible way in INSITE™ electronic service tool, verification of issue is **not** possible.

Resolution

- Do **not** use INSITE™ electronic service tool 8.2.0 to perform ECM calibration downloads.
- Use Cummins Inc. Update Manager to upgrade INSITE™ electronic service tool to version 8.2.1 immediately.

Document History

Date	Details
2017-3-20	Module Created
2017-4-24	Resolution Updated.

Last Modified: 25-Apr-2017
