



# Technical Service Bulletin

Technical Service Bulletin: TSB190077

Released Date: 15-May-2019

New Dual Impeller Water Pump Kit

## New Dual Impeller Water Pump Kit

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### Product Affected

- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK50 CM850 MCRS

#### Description of Change

A new improved dual impeller water pump has been released including:

- Additional lubricating oil drain orifices in water pump bearing housing
- New spring loaded rubber lubricating oil seal

#### Reason for Change

New dual impeller water pump provides more robust lubricating oil and coolant sealing by:

- Reducing the level of lubricating oil in water pump bearing housing.
- Including a more robust lubricating oil seal.

#### Service Instructions

- See Service Manual, bulletin number 4021528. Reference procedure 008-062 in Section 8.
- See Service Manual, bulletin number 4332823. Reference procedure 008-062 in Section 8.
- **Service Parts Availability**

Service parts are available. See Table 1 for part numbers.

| Table 1, Service Parts             |                      |          |            |                 |
|------------------------------------|----------------------|----------|------------|-----------------|
| Part Description                   | Existing Part Number | Obsolete | Superseded | New Part Number |
| QSK50 Dual Impeller Water Pump KIT | 4352353              | Yes      | Yes        | 5473148         |

## Document History

| Date      | Details        |
|-----------|----------------|
| 2019-5-14 | Module Created |

---

Last Modified: 15-May-2019

---